Halifax County

Bus #118: 2005 - 65 PASS FREIGHTLINER MBE900

Problem	Defect Points
Interior Condition: Loose Objects in Passenger Compartment	10
Brakes: Slacks need cleaning	5
Differential: Vent Needs Cleaning	5
Crossing Arm: Hinge Bushing Missing/Damaged	2
Battery: Hold Down Bar Corroded	5
Emergency Exits: Instructions Missing/Damaged	5
Air Conditioning: Filter Dirty/Loose/Damaged/Missing	5
Total Defect Points:	37

Inspected: 11/6/2013

Inspected: 11/7/2013

Bus #122: 2005 - 65 PASS FREIGHTLINER MBE900

Problem	Defect Points
Electrical Panel: Elec. Panel Loose/Damaged - WIRES BEEN HOT	5
Bus Parked: TIRES	50
Inspection: Excessive Axle/Tire Shimmy	10
Warning Lights: Lens Orientation Wrong	5
Passenger Seats: Cushions Not Secured (5-10)	10
Heater: Filter Dirty	5
Tire Tread Wear: Replace Left Rear Inner	15
Total Defect Points:	100

Thursday, November 07, 2013 Page 1 of 12

Halifax County

Bus #125: 2007 - 66 PASS INTERNATIONAL VT365E

Problem	Defect Points
Brakes: Slacks need cleaning	5
Interior Condition: Loose Objects in Passenger Compartment	10
Interior Panels/Lights: Light- Lens Damaged/Missing/Inoperable	2
Air Conditioning: Filter Dirty/Loose/Damaged/Missing	5
Driver Seat: Teathers loose or not adjusted	5
Total Defect Points:	27

Inspected: 11/6/2013

Inspected: 11/6/2013

Bus #135: 2008 - 66 Pass Freightliner MBE900

Problem	Defect Points
Brakes: Slacks need cleaning	5
Differential: Vent Needs Cleaning	5
Heater: Heater Inoperative	10
Entrance Door: Access Panel Loose/Damaged	2
Emergency Equipment: Belt Cutter Not in Side Pocket (07+ Model)	3
Total Defect Points:	25

Thursday, November 07, 2013 Page 2 of 12

Halifax County

Bus #142: 2008 - 66 Pass Freightliner MBE900

Problem	Defect Points
Mirrors: Right X-over Has Poor Reflectivity	10
Emergency Exits: Instructions Missing/Damaged	5
Heater: Panel/Filter Loose/Missing/Damaged	5
Lights: Repair Back-up Lights	5
Brakes: Slacks need cleaning	5
Total Defect Points:	30

Inspected: 11/6/2013

Inspected: 11/7/2013

Bus #187: 2001 - 66 PASS FREIGHTLINER CAT 3126 T

Problem	Defect Points
Bus Parked: BODY/CHASSIS ITEM	50
Mirrors: Right X-over Has Poor Reflectivity	10
Frame: Rear Cross Member Cracked/Bolts Loose - REAR TWO BEHIND AXLE	15
Passenger Seats: Frame Mounting Bolts Missing/Damaged	5
Heater: Motor Noisy	5
Floor Covering: Trim Missing/Loose/Damaged - FLOOR DAMAG	E 10
Total Defect Points:	95

Thursday, November 07, 2013 Page 3 of 12

Halifax County

Bus #199: 2010 - 66 Pass Freightliner Cummins ISB 6.

Problem	Defect Points
Load Range: Incorrect Left Rear Outer	15
Air Conditioning: Motor Noisy	5
Bus Parked: MULTIPLE SAFETY ISSUES (2-3) - DOORTIRES	75
Passenger Seats: Cover Damage (1-4 Seats)	5
Entrance Door: Will lock without Key	10
Body Damage: Left Side	5
Total Defect Points:	115

Inspected: 11/7/2013

Inspected: 11/6/2013

Bus #274: 1994 - 60 PASS FC NAVISTAR DT408 THO

Problem	Defect Points
Dash/Instrument Panel: Speedometer Broken/Inaccurate	10
Bus Parked: INTERIOR ITEM - SPEEDOMETER	50
Window Glass: Glass Fogging	5
Emergency Exits: Rear Door Handle/Guard Loose/Damaged	3
Heater: Motor Noisy	5
Switches: AC/Heater Switch/Motors/Fan Inoperable - DEF. ON HIGH	5
Total Defect Points:	78

Halifax County

Bus #310: 2011 - 72 Pass IC MaxxForce 7 Inspected: 11/6/2013

Problem	Defect Points
Air Conditioning: Filter Dirty/Loose/Damaged/Missing	5
Tire Tread Wear: Replace Left Rear Inner	15
Tire Tread Wear: Replace Right Rear Inner	15
Bus Parked: TIRES	50
Emergency Equipment: Fire Extinguisher Damaged/Not Secured - BRACKET LOOSE	10
Total Defect Points:	95

Bus #400: 1994 - 60 PASS FC NAVISTAR DT408 THO Inspected: 11/7/2013

Problem	Defect Points
Differential: Vent Needs Cleaning	5
Suspension: Front Spring Hanger bolts loose/missing	15
Interior Condition: Dirty/Mildew	5
Passenger Seats: Cushions Not Secured (1-4)	5
Drive Line: Shaft Out of Phase	5
Total Defect Points:	35

Halifax County

Bus #412:	1998 - 66 PASS FREIGHTLINER CAT 3126 T	
-----------	--	--

Problem	Defect Points
Dash/Instrument Panel: Speedometer Broken/Inaccurate	10
Passenger Seats: Cushion/Back Foam Damage (1-4 Seats)	10
Steering: Front End Needs Alignment	10
Differential: Vent Needs Cleaning	5
Steering: Tie Rod Adjusting Bar Damaged	20
Tire Tread Wear: Replace Right Front	15
Warning Lights: Repair Stop Sign Light	15
Lights: Repair Tail Lights	5
Bus Parked: MULTIPLE SAFETY ISSUES (4+)	100
Total Defect Points:	190

Bus #2807 1998 - 66 LIFT FREIGHTLINER CAT 3126 TH

Problem	Defect Points
Emergency Equipment: Fluid Spill kit not secured	3
Body Damage: Right Side	5
Brakes: Slacks need cleaning	5
Differential: Vent Needs Cleaning	5
Engine: Oil Leak	10
Exhaust: Tailpipe Loose/Damaged/Improper Length	5
Total Defect Points:	33

Inspected: 11/6/2013

Inspected: 11/6/2013

Halifax County

Bus #8115 1999 - 60 Pass Freightliner CAT 3126 A/C

Problem	Defect Points
Engine: Oil Leak	10
Wipers: Adjust Stroke / Not Parking	2
Differential: Vent Needs Cleaning	5
Lights: Repair Marker/Clearance Lights	5
Bus Parked: INOPERATIVE WARNING DEVICE - PANEL BUZZER	50
Emergency Exits: Panel Buzzer Inoperative - WHEN EMER.DOOR OPENS	15
Total Defect Points:	87

Inspected: 11/6/2013

Halifax County

Bus #8528 1993 - 66 Pass International DT360 Inspected: 11/7/2013

Problem	Defect Points
Brakes: Slacks need cleaning	5
Entrance Door Damaged	15
Bus Parked: MULTIPLE SAFETY ISSUES (2-3) - SEATSMIRRORSANTIFREEZE DRIPPING	75
Cooling System: Heater Hose Leak - ANTIFREEZE DRIPPING	5
Engine Cover: Repair Access Door	1
Driver Area: Interior Mirror Cracked/Broken/Loose	15
Mirrors: Incorrect Mirror/Brackets Installed - MISMATCHED TRAFFIC MIRRORS	15
Differential: Vent Needs Cleaning	5
Passenger Seats: Cushions Not Secured (11+)	15
Bus Parked: AEROSOL CAN OR UNLABLED CONTAINER	25
Exhaust: Hangers Loose/Missing	5
Emergency Exits: Rear Door Handle/Guard Loose/Damaged - MISSING	3
Lights: Repair Brake Lights (1)	5
Passenger Seats: Cushion/Back Foam Damage (1-4 Seats)	10
Driver Area: Interior Mirror Trim Missing/Damaged	2
Wipers: Replace Blades	5
Wipers: Window Washer Inoperative	10
Heater: Filter Dirty	5
Total Defect Points:	221

Thursday, November 07, 2013 Page 8 of 12

Halifax County

Bus #8530 2008 - 66 Pass International VT365 A/C

Problem	Defect Points
Mirrors: Right X-over Has Poor Reflectivity	10
Heater: Filter Dirty	5
Bus Parked: MULTIPLE SAFETY ISSUES (2-3) - BRAKE LIGHTSMIRRORS	75
Engine: Check Engine Performance - SKIPPING ON ROAD TEST	Г 15
Mirrors: Right Side Broken or Cracked - MISSING	10
Lights: Repair Brake Lights (2+) - NO BRAKE LIGHTS	15
Interior Panels/Lights: Light- Lens Damaged/Missing/Inoperable	2
Mirrors: Left X-over Mirror/Mount Loose - BENT	5
Air Conditioning: Filter Dirty/Loose/Damaged/Missing	5
Bus Parked: AEROSOL CAN OR UNLABLED CONTAINER	25
Mirrors: Left X-over Has Poor Reflectivity	10
Air Compressor: Air Supply Hose Loose/Damaged	5
Total Defect Points:	182

Inspected: 11/7/2013

Halifax County

Bus #8677 1997 - 36 Pass Ford 5.9 Inspected: 11/6/2013

Problem	Defect Points
Air Compressor: Air Compressor Oil Leak - DRAIN TUBE	5
Air Pressure: Improper on Rear Tires	5
Brakes: Left Front Lines Rubbing	5
Interior Panels/Lights: Panels Loose/Damaged - LOOSE AT DRIVER SEAT AT TETHER STRAP	2
Bus Parked: MULTIPLE SAFETY ISSUES (4+)	100
Entrance Door: Air Door Release Valve Loose - HANDLE IN WRONG POSITION	2
Wipers: Nozzles need adjustment	5
Floor Covering: Missing Trim Screws - AC HOSES SHEILD AT REAR	5
Emergency Equipment: First Aid kit not secured - not in box	3
Entrance Door: Access Panel Loose/Damaged	2
Interior Condition: Loose Objects in Passenger Compartment	10
Emergency Equipment: Fire Extinguisher Damaged/Not Secured	10
Emergency Exits: Rear Door Buzzer Inoperative	5
Emergency Exits: Rear Door Hold Open Mechanism Missing/Damaged/Loose	2
Exhaust: Hangers Loose/Missing - FRONT	5
Wiring/Hoses: Wires/Hoses Rubbing / Not Secured - ON EXHAUST REAR ENGINE	5
Passenger Seats: Cushion/Back Foam Damage (1-4 Seats) - BAR EXPOSED	10
Floor Covering: Trim Missing/Loose/Damaged - TRIP HAZARD	10
Emergency Exits: Panel Buzzer Inoperative	15
Differential: Vent Needs Cleaning	5
Heater: Heater Inoperative	10
Window Glass: Damage (1-2) - NOT OEM GLASS	5
Floor Covering: Unsealed Holes/Cracks	15
Battery: Tray not secured	10

Halifax County

Body Damage: Rear/Bumper	5
Fluid Level: Washer Fluid Low	5
Steering: Set/Adjust Wheel Stops - LEFT LOOSE	5
Brakes: Front Wheel Seal Damaged or Leaking - LEFT FRONT	15
Brakes: Slacks need cleaning	5
Battery: Hold Down Loose or Missing	10
Emergency Exits: Window/Roof Hatch Buzzer Inoperable - ALL OUT	5
Total Defect Points:	301

Bus #8680 2011 - 72 Pass Freightliner ISB 6.7L A/C

Problem	Defect Points
Emergency Equipment: Update Contents of First Aid Kit	5
Air Filter Assembly: Air Filter/Turbo Hoses Damaged/Missing	15
Emergency Exits: Ignition Interlock Not Functional	20
Entrance Door: Will lock without Key	10
Engine: Oil Leak	10
Air Conditioning: Filter Dirty/Loose/Damaged/Missing	5
Emergency Exits: Rear Door Hold Open Mechanism Missing/Damaged/Loose	2
Passenger Seats: Cover Damage (1-4 Seats)	5
Interior Condition: Loose Objects in Passenger Compartment - TRASH CAN	10
Bus Parked: MULTIPLE SAFETY ISSUES (2-3) - DOOR INTERLOCK NOT WORKING	75
Wipers: Replace Blades	5
Total Defect Points:	162

Inspected: 11/7/2013

School Bus Defect Report 2013-2014 Halifax County

Yellow Bus LEA Average = 71.67 Activity Bus LEA Average = 190.6